



Sony XPERIA Tablet Z Volume Button Replacement

Written By: Martin Luna



TOOLS:

Phillips #00 Screwdriver (1)

iFixit Opening Tool (1)


Tweezers (1)

Step 1 — Removing back cover




- Tools you will need is the Phillips #00 precision screwdriver, Plastic Opening Tools, and [tweezers](#).
- Insert plastic opening tool in the corner of device and slide along edges to separate adhesive.
- Remove cover
- Disconnect battery, to avoid electric shock, by pulling up on the white plastic as shown by the orange box.

Step 2 — Locate the Volume module




- Locate the volume module.
- Remove both screws using the Philips screwdriver.

Step 3 — Lift out of Place



- Once both screws are removed grab the tweezers.
- Then lift up on the module.

Step 4 — Removing the Electrical tape



- Find the electrical tape connecting the module to the motherboard
- Carefully pull out the electrical tape horizontally and remove the volume module from the device.

To reassemble your device, follow these instructions in reverse order.