

Polk MagniFi Soundbar Bluetooth Cable Replacement

The bluetooth is not connecting even though you have troubleshooted.

Written By: D'Lana Pearce



INTRODUCTION

This guide will show you how to swap out the bluetooth sensor in your soundbar. Keep in mind this is a fragile cable that can easily be broken. It must be handled with care.




TOOLS:

- iFixit Opening Tools (1)
- Mako Driver Kit 64 Precision Bits (1)

Step 1 — Bluetooth Cable







- To reveal the control button, first, carefully remove the front cover of the Sound Bar.
- Use the plastic iFixit opening tool to lift up the front surface. Insert the tool between the cover and the body to open it.
- After the cover is fully removed, it will be able to see the interior speaker.
- Carefully unscrew all 16 screws to release the panel.
 - There are total 16 screws that secures the panel onto the cover. Each screw is approximately 1.50 centimeter.

Step 2








- To remove the cover behind the control buttons, insert the iFixit opening tool between the cover and the body
- Push the opening tool along the edge of the cover to fully open it.

Step 3



 Underneath the cover, there is a black panel screwed onto the cover with two sets of wires plugged into it.

Step 4





- Grasp the wire firmly close to the base and pull straight out. Repeat this for the other end of the wire.
- ↑ This wire is easily broken. Handle with care.

To reassemble your device, follow these instructions in reverse order.